



DET NORSKE VERITAS

MANAGEMENT SYSTEM CERTIFICATE

Sertifikat nr. 74740-2010-AHSO-NOR-NA

Med dette bekreftes at Arbeidsmiljø- og Sikkerhetssystemet ved

BIS Production Partner Norge Vest

Årdalstangen, Øvre Årdal, Høyanger, Sunndalsøra, Karmøy og Porsgrunn

oppfyller kravene i

OHSAS 18001:2007

Dette sertifikatet er gyldig for følgende områder/tjenester:

**Planlegging og gjennomføring av
vedlikeholds-, verksteds- og ildfaste industrimuringstjenester.
Prosjektering, prosjektledelse og gjennomføring av
ildfaste installasjoner og øvrige industriprosjekter innen elektro, mekanisk og bygg.**

Første sertifikat gyldig fra:

2010.03.23

Sertifikatet er gyldig til:

2013.03.23

Ansvarlig for revisjonen:

Thomas Haug
Revisjonsleder



Sted og dato:

Høvik, 2010.03.25

For akkreditert enhet:

**DET NORSKE VERITAS
CERTIFICATION AS**

Jan R Brembo
Jan Roald Brembo
Ledelsens representant

Brudd på forutsetningene for sertifikatet, slik det fremgår av vedlegget, kan gjøre sertifikatet ugyldig.



DET NORSKE VERITAS

MANAGEMENT SYSTEM CERTIFICATE

Certificate No. 74740-2010-AHSO-NOR-NA

This is to certify that the Management System of

BIS Production Partner Norway West

at

**Årdalstangen, Øvre Årdal, Høyanger, Sunndalsøra, Karmøy and Porsgrunn
Norway**

has been found to conform to the Occupational Health and Safety Management System Standard(s):

OHSAS 18001:2007

This Certificate is valid for the following product or service ranges:

**Planning and execution of maintenance-, workshop- and refractory services.
Engineering, project management and execution of refractory installations
and industrial projects within electrical, mechanical and civil works.**

Initial Certification date:

2010.03.23

This Certificate is valid until:

2013.03.23

*The audit has been performed under the
supervision of*

Thomas Haug
Lead Auditor



Place and date:

Høvik, 2010.03.25

for the Accredited Unit:
**DET NORSKE VERITAS
CERTIFICATION AS, NORWAY**


Jan Roald Brembo
Management Representative

Lack of fulfilment of conditions as set out in the Certification Agreement may render this Certificate invalid.